

TROUBLESHOOTING GUIDE INDEX FOR TRANSFER MOLDING BMC

<u>Topic</u>	<u>Page</u>
Philosophy Of Troubleshooting Molding Proble	Transfer 1
Transfer Processing Problems	Transfer 2
Crazing / Cracking	Transfer 2
Contamination	Transfer 3
Dieseling	Transfer 3
Drag Marks	Transfer 3
Dull Appearance	Transfer 4
Flash (Excessive)	Transfer 4
Flow Lines	Transfer 4
Knit Lines	Transfer 4
Laking	Transfer 5
Nonfills Or Short Shots	Transfer 5
Pin Cracking	Transfer 5
Pre Cure	Transfer 5
Shrinkage	Transfer 6
Sink Marks	Transfer 6
Sticking In Mold	Transfer 6
Trapped Gas (Burn Marks)	Transfer 7
Warpage	Transfer 7
Troubleshooting Chart and Comment Sheet	Inserts